A Safe Workplace

A Workplace Safety and Health Manual for Your Community

Section:	Rules Procedures, Practices		Page 1 of 1
III-D	and Guidelines	Approved By: Harvey Bostrom	
Subject:	Operating an Electric Power	Effective: April 01, 2005	
TSE-2	Drill	Revised: April 1, 2011	

PPE Required: Safety glasses or face shield, hearing protection, steel-toe boots

Warning: Do not wear loose clothing or rolled up sleeves

Remove all jewelry

Disconnect the power before repairing or servicing

Ensure cord is not in water and that the tool is grounded or double-

insulated.

Steps:

1. Read and understand equipment manual before operating circular saw.

- 2. Ensure drill is unplugged prior to changing bits or doing maintenance on drill.
- 3. Layout-out work and mark area to be drilled.
- 4. Drill on 90 degree angle to materials.
- 5. Ensure a firm grip on drill. Bend arms slightly to absorb shock if bit grabs.
- 6. Ensure the work area is free of debris and obstructions.
- 7. Plug in and start the drill. Check for rotation and wobble.
- 8. Begin drilling material. Keep both hands firmly on the tool handles and use clamps to secure work.
- 9. Remove bits and store drill. Do not leave on scaffold or ladder. Clear the work area of debris.